



November 15, 2023

# Move-in Inspection

Completed by:

**Alexa Younger**

alex@getrentcheck.com

---

Completed on:

**November 15, 2023**

---






Address:

**515 Atalin Street, Mandeville 70448**

# Summary

Content	Rating Percentage	Good	Fair	Poor	Flags	Link
Table of Contents						<a href="#">🔗</a>
Kitchen	<div style="width: 100%; height: 10px; background-color: #4CAF50;"></div>	100% Good	0% Fair	0% Poor		<a href="#">🔗</a>
First Full Bathroom	<div style="width: 100%; height: 10px; background-color: #4CAF50;"></div>	100% Good	0% Fair	0% Poor		<a href="#">🔗</a>
Office	<div style="width: 100%; height: 10px; background-color: #4CAF50;"></div>	100% Good	0% Fair	0% Poor		<a href="#">🔗</a>
General	<div style="width: 50%; height: 10px; background-color: #4CAF50; display: inline-block;"></div> <div style="width: 50%; height: 10px; background-color: #FF9800; display: inline-block;"></div>	50% Good	50% Fair	0% Poor		<a href="#">🔗</a>

# Table of Contents


Room/Area	Feature	Maintenance	No	Inspection Notes	Images	Rating	View
Kitchen	Kitchen				7	 <b>Good</b>	<a href="#">View</a>
First Full Bathroom	Full Bathroom				4	 <b>Good</b>	<a href="#">View</a>
Office	Office				1	 <b>Good</b>	<a href="#">View</a>
General	Exterior			Some debris. Send cleaning crew.	2	 <b>Fair</b>	<a href="#">View</a>
General	General				1	 <b>Good</b>	<a href="#">View</a>

# Kitchen Kitchen

Flags 0 Images 7 Rating Good



[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)

# First Full Bathroom Full Bathroom

Flags 0 Images 4 Rating Good



[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)

# Office Office

Flags 0 Images 1 Rating **Good**



[View Image](#)

# General Exterior

Flags 0 Images 2 Rating **Fair**



**Alexa Younger** November 15, 2023  
Some debris. Send cleaning crew.



[View Image](#)



[View Image](#)

# General

## General

Flags 0 Images 1 Rating Good



[View Image](#)

## Inspection completed

The signatory has confirmed that they have performed this inspection and that it is current, accurate and complete to their knowledge.

A handwritten signature in black ink, appearing to read 'A Younger', is centered within a light gray rectangular box with a dashed border.

Alexa Younger  
Property Manager  
Signed on 11/15/2023

---